

MA073494

# CABIN HAZARDS FROM A LARGE EXTERNAL FUEL FIRE ADJACENT TO AN AIRCRAFT FUSELAGE

Louis J. Brown, Jr.

AL CONTAINS COLOR PLATES: ALL DDC



SEP 7 1979

**AUGUST 1979** 

FINAL REPORT

Document is available to the U.S. public through the National Technical Information Service, Springfield, Virginia 22161.

Prepared for

U.S. DEPARTMENT OF TRANSPORTATION
FEDERAL AVIATION ADMINISTRATION
Systems Research & Development Service
Washington, D.C. 20590

DIC FILE COPY

## NOTICE

The United States Government does not endorse products or manufacturers. Trade or manufacturer's names appear herein solely because they are considered essential to the object of this report.

Repart No. 2. Government Acces	ssion No. 3. Recipient's Catalog No.
FAA-RDH79-65	
Tirle and Sobrirle	5. Report Date
CABIN HAZARDS FROM A LARGE EXTERNA	L FUEL AL August 19
FIRE ADJACENT TO AN AIRCRAFT FUSEL	
	8. Performing Organization Report No.
Author(s)	o. Performing Organization Report No.
(10) Louis J./Brown, Jr/	144 FAA-NA-79-27
Performing Organization Name and Address	10. WOR UNIT NO. ((RAIS)
ederal Aviation Administration	TE TATE   4 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
lational Aviation Facilities Experimenta	1 Center 11. Contract or Grant No. 7
tlantic City, New Jersey 08405	181-521-100
	13. Type of Report and Period Covered
. Sponsoring Agency Name and Address	
J.S. Department of Transportation	(9) Final repto
ederal Aviation Administration	14. Sponsoring Agency Code
Systems Research and Development Service	The special state of the speci
Vashington, D.C. 20590	
	V
1	2)51p.
Ourteen fire tests were conducted with positioned adjacent to a 20-foot-square opening at the center of the fire and do	a surplus, fire-hardened DC7 fuselage JP-4 fuel fire. The fuselage had a door or openings displaced from the fire on
Fourteen fire tests were conducted with cositioned adjacent to a 20-foot-square pening at the center of the fire and do each side of the fuselage. Temperatures were measured for each of these 90-second the fire was varied from test to test as direction coupled with the door opening factors in the accumulation of heat and fluxes into the cabin through the fire d and door openings and depended on the deloor. When flames did not penetrate into	a surplus, fire-hardened DC7 fuselage JP-4 fuel fire. The fuselage had a door or openings displaced from the fire on , light transmittances, and heat fluxes d tests. The opening of doors away from was the ambient wind velocity. Wind configuration were found to be controlling smoke within the aircraft cabin. Heat oor also changed significantly with wind gree of flame penetration through the fire o the cabin, the symmetry plane heat flux
Fourteen fire tests were conducted with cositioned adjacent to a 20-foot-square opening at the center of the fire and do each side of the fuselage. Temperatures were measured for each of these 90-second the fire was varied from test to test as direction coupled with the door opening factors in the accumulation of heat and fluxes into the cabin through the fire daind door openings and depended on the dedoor. When flames did not penetrate into the fire door station agreed very well addiation from the fire door station agreed very well fire.	a surplus, fire-hardened DC7 fuselage JP-4 fuel fire. The fuselage had a door or openings displaced from the fire on , light transmittances, and heat fluxes d tests. The opening of doors away from was the ambient wind velocity. Wind configuration were found to be controlling smoke within the aircraft cabin. Heat oor also changed significantly with wind gree of flame penetration through the fire o the cabin, the symmetry plane heat flux l with earlier modeling predictions.  18. Distribution Statement Document is available to the U.S. public through the National Technical Information
Fourteen fire tests were conducted with cositioned adjacent to a 20-foot-square opening at the center of the fire and do each side of the fuselage. Temperatures were measured for each of these 90-second the fire was varied from test to test as direction coupled with the door opening factors in the accumulation of heat and fluxes into the cabin through the fire daind door openings and depended on the dedoor. When flames did not penetrate into the fire door station agreed very well addiation	a surplus, fire-hardened DC7 fuselage JP-4 fuel fire. The fuselage had a door or openings displaced from the fire on , light transmittances, and heat fluxes d tests. The opening of doors away from was the ambient wind velocity. Wind configuration were found to be controlling smoke within the aircraft cabin. Heat oor also changed significantly with wind gree of flame penetration through the fire o the cabin, the symmetry plane heat flux l with earlier modeling predictions.  18. Distribution Statement Document is available to the U.S. public

For DOT F 1700.7 (8-72)

Unclassified

Unclassified
Reproduction of completed page authorized

240550

top

Symbol   Symbol   When Yee Keew   Meltight by   To Find	Symbol   Symbol   When Yes Keep   Bailipy by   To Find		l	1123	i	171	8.2	= K + 15.5	,
			!	Hit	1	square inches square yards aquare miles acres	ounces pounds short tons	fluid ounces pirits quarts gallons cubic yards	Fabrantesi temperature
		ns from Metric	ENGTH	9.04 3.3 1.1	970	0.16 1.2 0.4 2.5	0.036 2.2 1.1	0.03 2.1 1.06 0.26 35 1.3	J/S (then add 32)
		Approximate Conversion	ua U	millimeters Centimeters meters meters		square continues square square maters square kilometers hectares (10,000 m²)	9 8		Celsius
	. 22 23 . 25 £323 £338	2	ļ	<b>E</b> 5 e e	5	~E~E~E #	o 2 -	Ē "E"E	741
	. 1911 1919 4 1919 4 1919 4 1919 4 1919 4 1919 4 1919 4 1919 4 1919 4 1919 4 1919 4 1919 4 1919 4 1919 4 1	5							
	of a chiral distance and are the sound and the second to be a control of the chiral second to	CONVENSION FACTOR		.1.1.1.1.1.1					
To Find  Continuents  Continuents  meters  kilometers  aquere meters  cobic meters  cubic meters				 	e <b>5</b>	Attimeters on the state of the	   -  -  -  -  -  -  -  -  -  -  -  -	EEE@7	
LENGTH  1.5 Continuous  3.0 Co	LENGTH  1.6 AREA  2.5 30  2.9 3.0  2.9 3.0  2.8 0.09  2.8 0.09  2.9 0.09  2.9 0.09  2.9 0.09  2.9 0.09  2.0 0.09  2.	40000 00 68 0000 6900 0 19 000 10000	Symbol Symbol To Flad Symbol S	Continuotes	9 meters m 6 kilometers km	square centimaters cm² 9 square maters m² square maters m² square maters m² square kilometers km² hectares ha	grams biograms townes connection	militiers mi militiers mi liters liters — — — — — — — — — — — — — — — — — — —	Celsius °C
Metric Messure  Continue Continue Continue Continue Continue Square Squa	When Yes Knew Meltiphy by  inches 72.5 feet 30 yards 0.9 water inches 0.9 square inches 0.0 square	4 3 1 4 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5	Multiply by To Find Symbol	12.5 continuers on	0.9 meters m 1.6 kilometers km	6.5 square centineters cm² o con square meters m² con square meters m² con square hilometers km² con square km² con squar	28 grams 9	5 milliliters ml 15 milliliters ml 30 milliliters ml 0.47 liters liters 0.95 liters liters 1 0.03 cubic meters	MPERATURE (exact)  5/9 (after Celsius °C  sobteacting temperature

## PREFACE

The assistance of Messrs. Joseph A Wright, Franklin D. Fann, and Lawrence J. Curran in the varying activities of instrumentation, testing, and data analysis is acknowledged. The helpful advice of and useful discussions with Dr. Thor Eklund are also acknowledged.

ccession		TE -
NTIS GRA	ET	
in announc	ed '	
Justifica	tion_	محسس
ВУ		
Distribu	tion/	
Availab	4111V	Codes
Availar	33.00	alor
	vail an	1
Dist	specie	11
h		

## TABLE OF CONTENTS

		Page
INTRODUCTION		1
Purpose	Porward View of DCT Intelloc	1
Background Experimental Objective		1
DISCUSSION		1
Test Procedure Test Results and Analysis		1 3 3 7
SUMMARY OF RESULTS		23
CONCLUSIONS	Celling Heat First under Calm Wind Combulions-Tosts 43 and 18	26
REFERENCES		26
APPENDICIES		
A Laser Transmissometer P. B Temperature Stratificat		

Sugmerry Plane Heat Plux with Wind Persendicular

# LIST OF ILLUSTRATIONS

Figure		Page
1 1	Fire-Hardened Fuselage	2
2	Forward View of DC7 Interior	4
3	Thermocouple, Calorimeter, and Laser Transmissometer Locations	5
4	Aft View of DC7 Interior	6
5	Ceiling Temperature History under Calm Wind ConditionsTests 13 and 14	10
6	Symmetry Plane Heat Flux under Calm Wind ConditionsTests 13 and 14	11
7 88	Ceiling Heat Flux under Calm Wind ConditionsTests 13 and 14	12
8	Flame PenetrationTest 13	13
9	Calm Wind ConditionTest 13	14
10	Fire WhirlTest 14	15
11	Ceiling Temperature History with Wind Perpendicular to FuselageTests 3, 4, 9, and 10	17
12	Ceiling Heat Flux with Wind Perpendicular to FuselageTests 4 and 10	18
13	Ceiling Heat Flux with Wind Perpendicular to FuselageTests 3 and 9	19
14	Moderate Breeze ConditionTest 3	20
15	Flame PenetrationTest 9	21
16	Symmetry Plane Heat Flux with Wind Perpendicular to FuselageTests 3, 9, and 10	22
17	External Skin Heat FluxTests 4, 8, and 13	24

# LIST OF TABLES

Table		Page
1	Beaufort Wind Scale	8
2	Summary of Test Conditions	9
3	Relative Severity of Tests 3, 4, 9, 10, 13, and 14	25

#### INTRODUCTION

#### PURPOSE.

The purpose of this project was to measure and study the flame penetration and resulting accumulation of heat and smoke inside an aircraft cabin produced by a large external fuel fire adjacent to a fuselage door opening.

#### BACKGROUND.

During an impact-survivable crash, the cabin interior can be threatened by a possible external fuel fire. Heat, smoke, and toxic gases may enter the cabin through fuselage openings and create hazardous conditions within a short period of time (reference 1).

Full-scale tests on the effect of large pool fires on a fuselage have produced heat transfer rates to the exterior as high as 13 British thermal units per foot squared second (Btu/ft<sup>2</sup>s) (reference 2) in one set of tests, 16 Btu/ft2s in another (reference 3), and 18 Btu/ft2s in tests on a titanium fuselage (reference 4). These heat fluxes are upper extremes that can be realized from a large fuel fire. Wind conditions, door opening Facilities Experimental Center tion from test to test.

(reference 5). A full-scale test as reported herein was needed to confirm and validate heat and smoke measurements obtained in other modeling and small-scale tests.

#### EXPERIMENTAL OBJECTIVE.

The experimental objective of this project was to conduct full-scale tests to study the effect of large external pool fires adjacent to an aircraft fuselage door opening.

#### DISCUSSION

### GENERAL APPROACH.

Tests were performed at NAFEC's airport fire test site utilizing an existing 400-ft2 fire pit. A strippedout, surplus DC7 fuselage (previously first used by Marcy (reference 6) for aircraft interior materials testing) was prepared as a test article (figure 1). To preserve the aluminum fuselage for more than one test, the aircraft skin was "fire-hardened" with galvanized steel sheeting (0.032 inches thick) placed over Kaowoo 19 noncombustible aluminosilicate fiber blankets (1 inch thick). The fire hardening extended 20 feet on either side of the fire doorway from the top configurations, breaks in the to the bottom centerlines of the fuselage, or "burn-throughs" can be fuselage. Two additional doorways expected to cause great variability were cut on each side of the fuselage in the cabin hazard levels. The cabin approximately 30 feet forward of the hazards resulting from a small fuel fire doorway. These doorways were fire adjacent to an intact fuselage fitted with removable metal covers. door opening have been more recently This was accomplished for the purpose studied at the National Aviation of varying the door opening configura-All three (NAFEC) in full-scale C133 tests doorways measured 28 inches wide by (reference 1). Physical fire 56 inches high. These door dimensions modeling tests were also performed to properly scale the Type A doorway examine the Cl33 cabin environment openings in the Cl33 (76 inches under large fuel fire conditions by 42 inches) and fire modeling




FIGURE 1. FIRE-HARDENED FUSELAGE

(19 inches by 10.5 inches) test articles. The interior was firehardened to varying degrees (depending on the proximity to the fire door) using Kaowool, fiberglass cloth, galvanized and stainless steel sheets, and transite. Extra effort went into stripping out combustible materials (insulation, hatracks, etc.) especially on the fire side of the The test article was fuselage. positioned with the fire doorway at the center of one side of the firepit (figures 1 and 3).

## INSTRUMENTATION.

Instrumentation consisted of calorimeters, thermocouple trees, laser transmissometers, motion picture and still photography, and a windspeed and direction indicator. Laser transmissometer, windspeed, and calorimeter data were recorded on a Honeywell model 1858 oscillograph. Thermocouple data were recorded on an Esterline Angus model D2020 digital data logger. Both recorders were located in an instrumentation trailer near the fuselage. Plan and side views of the cabin interior show calorimeter, thermocouple, and laser transmissometer locations (figure 3). Three calorimeters (Hy-cal model C-1300-A) were installed at locations that correspond to those of the C133 and physical fire modeling test articles. These locations include the ceiling (C2), exterior skin (C3) (adjacent to the fire doorway), and the symmetry plane of the doorway (C1) (figures 2 and 3). Two thermocouple trees, each consisting of four chromel-alumel thermocouples, were Two helium-neon laser trans-

Physics model 155, wavelength = 632.8 nanometers) and photocells (Weston model 856 YR) were covered with fiberglass cloth over Kaowool blankets for protection from the harsh environment (figure 4). A Trade-Wind cup anemometer (model 110) was positioned next to the instrumentation trailer and used to record wind velocities continuously on the oscillograph. Wind direction was manually recorded from a Taylor Windscope (model 3105) direction indicator. Four motion picture cameras were used to document the tests.

### TEST PROCEDURE.

A set routine was followed in preparing for and conducting each test. The fire pit was first filled with water to a depth that sufficiently covered the gravel bed. One hundred gallons of JP-4 fuel was pumped from a fuel tanker truck into the pit. Calorimeter cooling lines were checked for proper water flow and laser transmissometer windows were cleaned.

Calibration checks were performed on the oscillograph and thermocouple Firemen prepared for recorders. extinguishing the fire. With all instruments operational, a signal was given to first start the motion picture cameras and then to light the fire pit with a torch. duration was 90 seconds, at which time a signal was given for the firemen to extinguish the fire using light-water. Although a longer test duration may have been desirable, 90 seconds was adequate to allow for the development of cabin hazard level conditions used to record temperatures within the reflecting wind and door opening configurations and was believed missometers were mounted horizontally not to unduly jeopardize the test at different heights to span a 3-foot article. The fire pit was then pumped cross-section of the cabin (Ll top and out to prepare for another test. L2 bottom). The lasers (Spectra Repeated early morning tests were





FIGURE 2. FORWARD VIEW OF DC7 INTERIOR



THERMOCOUPLE, CALORIMETER, AND LASER TRANSMISSOMETER LOCATIONS FIGURE 3.




FIGURE 4. AFT VIEW OF DC7 INTERIOR

conducted in an attempt to obtain a calm (reference 7) wind condition (table 1) for baseline data.

#### TEST RESULTS AND ANALYSIS.

Table 2 summarizes the initial conditions of the 14 tests which were conducted during November 1978. In one category of tests, the cabin hazard levels were low compared to the remaining test results. These low results were obtained when the wind direction was parallel to the Peak symmetry-plane fuselage. heat flux was less than 1.2 Btu/ft2s, and peak ceiling temperature at T1 (figure 3) was less than 200 degrees Fahrenheit (°F). A test with the wind blowing the fire in a direction away from the fuselage (test 8) also produced low results similar to the parallel wind tests. It became clear from observers' tape recorded reports and exterior movie coverage that the fire doorway was visible during this category of tests, indicating that cabin exposure conditions were not representative of a realistic, large fire. Fuselage skin calorimeter (C3) output averaged less than 5 Btu/ft2s, thus confirming the low cabin environmental readings that were recorded for these tests.

The remaining tests, which produced significantly higher hazards, fall into two categories. One of these categories is the calm wind condition during which test 13 (all doors open (ADO)) and test 14 (all doors closed (ADC)) were conducted. Significant differences in heat accumulation for these two tests are (figure 5). continued to increase when the doors were open, but leveled off at 50 seconds when the doors were closed.

These same trends can be seen in the responses of the symmetry plane and ceiling calorimeters (figures 6 and 7, respectively) and the light transmittance data for the bottom laser transmissometer (see appendix A page A-3). It is evident from both photography (figure 8) and the ceiling calorimeter data that there was significant flame penetration during test 13. Smoke and heat filled the cabin and vented out of both forward doorways (figure 9). Test 14 experienced much less flame penetration, as evident in the ceiling calorimeter data (figure 7). Subsequently, less accumulation of heat and smoke occurred during test 14 as compared with test 13. A fire whirl (reference 8) developed during test 14 (figure 10) causing intense radiant heat to be felt by test personnel. However, skin calorimeter output at the fire door for test 14 showed that the fire whirl did not appear to have adversely affected the test results as compared with test 13.

A numerical integration was performed on the symmetry plane calorimeter plot for these two tests. The heat fluxes from 20 seconds (time when fire becomes fully developed) to 70 seconds (time when most readings began to dropoff) averaged 2.4 Btu/ft2s and 1.8 Btu/ft2s for tests 13 and 14, respectively. A heat flux of 1.8 Btu/ft2s was obtained during modeling tests for an "infinite" fire under quiescent wind conditions (reference 5). A higher average symmetry plane heat flux for test 13 is attributed to the flame penetration documented during the test which was apparent in the plot of the rear significantly greater than in test 14. ceiling thermocouple's (T1) outputs The variation in door opening Cabin temperature configuration appeared to be the controlling factor in these two tests.

TABLE 1. BEAUFORT WIND SCALE \*

Windsp	eed		
mi/h	<u>kn</u>	Description	Observation
0-1	0-1	Calm	Smoke Rises Vertically
1-3	1-3	Light Air	Smoke Drifts Slowly
4-7	4-6	Slight Breeze	Leaves Rustle
8-12	7-10	Gentle Breeze	Leaves and Twigs in Motion
13-18	11-16	Moderate Breeze	Small Branches Move
19-24	17-21	Fresh Breeze	Small Trees Sway

<sup>\*</sup> Beaufort wind scale is used because of its simple way in defining the minor variation in wind velocities encountered during testing (reference 7).

TABLE 2. SUMMARY OF TEST CONDITIONS

Test No.	Date	Time (EST)	Wind Condition (1)	Wind Direction (Degrees) (2)	Ambient Temperature (F)	Door Configuration (3) (4) (5)
-1	11/15/78	0636	celm		57	ADO
2	11/15/78	1046	slight to gentle breeze	0	65	ADO
3	11/18/78	0950	moderate breeze	270	55	UDO (2R closed)
4	11/18/78	1249	gentle breeze	270	68	DDO (2L closed)
5	11/19/78	0655	light air	315	34	ADO
6	11/20/78	0621	light air	0	38	ADO
7	11/21/78	0623	slight breeze		41	ADO
8	11/21/78	1427	slight to gentle breeze	060	57	ADO
9	11/24/78	0621	slight to gentle breeze	270	56	ADO
10	11/24/78	1054	gentle to moderate breeze	270	64	ADC (2R and 2L closed)
11	11/26/78	0652	light air to slight breeze	0	34	ADO
12	11/28/78	1003	slight breeze	0	43	ADO
13	11/29/78	0630	calm		31	ADO
14	11/29/78	1406	calm to light air	270	49	ADC (2R and 2L closed)







FIGURE 5. CEILING TEMPERATURE HISTORY UNDER CALM WIND CONDITIONS--TESTS 13 AND 14



SYMMETRY PLANE HEAT FLUX UNDER CALM WIND CONDITIONS-TESTS 13 AND 14 FIGURE 6.



CEILING HEAT FLUX UNDER CALM WIND CONDITIONS--TESTS 13 AND 14 FIGURE 7.






FIGURE 9. . CALM WIND CONDITION--TEST 13




FIGURE 10. FIRE WHIRL--TEST 14


Appendix B contains temperature stratification data during tests 3, 4, 9, 10, 13, and 14 for both thermocouple trees. These plots clearly show the variation in the distribution of heat between the cabin floor and ceiling from test to test.

Tests 3, 4, 9, and 10 were conducted with the wind perpendicular to and blowing the fire toward the fuselage. Wind conditions and exit door configurations differed for the four tests. A graph of Tl's output shows the variation in heat accumulation for these tests (figure 11). A peak ceiling temperature of 1,400° F was recorded during test 4 (appendix B page B-3). This severe temperature is attributed to downwind door open (DDO) and the upwind door closed (UDC). Such a door opening configuration caused high cabin drafts carrying vast amounts of smoke and heat to flow through the length of the cabin. appears that the low-pressure downwind opening draws air and combustion products from the fire door through the cabin. In contrast, in test 3 when the wind velocity was higher than in test 4 but the forward door opening locations were reversed, heating of the cabin air was much lower. In this upwind door open (UDO) case, ambient wind entering the cabin appeared to act like a buffer against the expanding fire gases. Evidence of severe flame penetration during test 4 is apparent in the ceiling heat fluxes which were in excess of 5 Btu/ft2s (figure 12). Light transmission data for the bottom laser (appendix A page A-1) showed smoke accumulation occurring as early as 10 seconds into test 4 and total obscuration of the 3-foot light beam by 25 seconds. Test 3, in contrast, experienced very little flame penetration (ceiling calorimeter plot--figure 13) even though the doorway was observed to be


covered by fire during the entire test (figure 14). Similar to temperature, smoke accumulation for test 3 (appendix A page A-1) was the lowest of the four wind tests. Only the upwind doors were open during test 3, preventing any crossflow from the upwind to downwind sides through the fuselage. This door opening configuration also allowed ambient wind to enter the cabin through the forward doorway and block expansion of the fire gases.

The ceiling calorimeter outputs for test 9 (ADO) and test 10 (ADC) are included in figures 13 and 12, respectively. Intermittent flame penetrations occurred during tests 9 and 10. More severe flame penetrations in test 9 produced a higher accumulation of heat (appendix B page B-5) and a more rapid accumulation of smoke (appendix B page B-2) than during test 10. More smoke and heat inside the cabin when all doors are opened as opposed to when all doors are closed, with wind, produced the same trend as with calm wind conditions (figure 5). Figure 15 shows flame penetration during a perpendicular wind test (test 9). smoke layer is evident near the top of the doorway.


A numerical integration of the symmetry plane calorimeter's output from 20 to 70 seconds for tests 3, 9, and 10 produced average heat fluxes of 1.4, 2.4, and 1.6 Btu/ft2s, respectively (figure 16). Test 4 produced symmetry plane heat fluxes greater than the recordable range (4 Btu/ft2s) for most of the test. Symmetry plane calorimeter results of test 4 and 9 are attributed to the degree of flame penetration apparently controlled by the door opening configuration. During both of these tests, smoke and heat could enter on the



CEILING TEMPERATURE HISTORY WITH WIND PERPENDICULAR TO FUSELAGE--TESTS 3, 4, 9, AND 10 FIGURE 11.



CEILING HEAT FLUX WITH WIND PERPENDICULAR TO FUSELAGE -- TESTS 4 AND 10 FIGURE 12.




CEILING HEAT FLUX WITH WIND PERPENDICULAR TO FUSELAGE-TESTS 3 AND 9 FIGURE 13.



FIGURE 14. MODERATE BREEZE CONDITION--TEST 3



FLAME PENETRATION



SYMMETRY PLANE HEAT FLUX WITH WIND PERPENDICULAR TO FUSELAGE--TESTS 3, 9, AND 10 FIGURE 16.

upwind side and exit on the downwind side of the fuselage. These tests (4 and 9) permitted a "forced" flow through the cabin. However, when the forced flow is blocked (tests 3 and 10), a less severe environment results within the cabin.

Skin Calorimeter (C-3) outputs tended to confirm the observed flame coverage of the fire door during the tests. Low accumulation of heat and smoke corresponded to low skin calorimeter outputs; i.e., similar to those of test 8 (figure 17). The high, steady exterior calorimeter output during test 13 (14 Btu/ft2s) is indicative of consistent flame coverage of the fire door with calm wind conditions. Test 4 produced a similar high exterior calorimeter output; however, the presence of wind caused random fluctuations (+6 Btu/ft<sup>2</sup>s) about the 14 Btu/ft<sup>2</sup>s average.

Table 3 summarizes the relative severity of the two calm wind condition tests and the four tests in which a gentle-to-moderate breeze was blowing the fire toward the fuselage. Excluding tests 3 and 4 (in which varying door opening configuration broadened the possible spectrum of results), the average symmetry plane heat flux falls into a range of 1.6 to 2.4 Btu/ft2s. For the calm wind condition tests (13 and 14), the symmetry plane heat flux falls into a range of 1.8 to 2.4  $Btu/ft^2s$ .

Table 3 also includes temperature and smoke hazard data. It is clear from elapsed times to the arbitrary  $T2 = 200^{\circ} F$  and  $400^{\circ} F$  and L2 = 50and 10 percent values, that the smoke hazard precedes the temperature hazard in the cabin for these tests. temperature, and heat flux.

#### SUMMARY OF RESULTS

- With the wind parallel to the fuselage, very little accumulation of heat and smoke resulted within the cabin due to incomplete flame coverage of the fire door opening. A test with the fuselage upwind of the fire produced similar results.
- 2. Tests were conducted with calm wind conditions, in one case with all doors open (ADO) and in another case with all doors closed (ADC). With ADO, the average symmetry plane heat flux was 2.4 Btu/ft2s. With ADC, the average symmetry plane heat flux was 1.8 Btu/ft2s.
- 3. The heat flux to the external skin calorimeter averaged about 14 Btu/ft2s for calm wind condition or steady, perpendicular wind (blowing fire toward fuselage) tests.
- 4. Depending on wind direction and speed and door opening configuration, the average heat to the symmetry plane calorimeter at the fire door can vary from 1.0 Btu/ft2s (wind pushing fire away from fuselage) to values in excess of 4 Btu/ft2s (wind driving fire into doorway with downwind door open).
- Four tests were conducted with a gentle-to-moderate breeze blowing the fire toward the fuselage. opening configurations were found to control the flow of heat and smoke into the cabin. The most hazardous cabin environment for these tests occurred when the upwind door was closed and the downwind door was open. Conversely, the least hazardous environment occurred when the upwind door was open and the downwind door In addition, similar trends in the was closed. When either all doors relative severity are shown for smoke, were open or all doors were closed,




FIGURE 17. EXTERNAL SKIN HEAT FLUX--TESTS 4, 8, and 13

TABLE 3. RELATIVE SEVERITY OF TESTS 3, 4, 9, 10, 13, and 14

			100			13	010	391	
F .	Door	Wind	Symmetry Plane Reat Flux (Btu/ft2s)	Average Ceiling Heat Flux (Btu/ft2s)	To Temper of 2000 F	To Temperature, T2	To Light To of 50%	To Light Transmission, L2, of 50% of 10%	2,
	ogn	moderate	1.4	1.2	. 67	1	52	69	
•	ADC	gentle to	1.6	3.1	3	**************************************	67	3	
•	ADC	calm	8.1	2.5	n	8	*	28	
9	ADO	cala	2.4	5.6	20	19	*	3	
•	900	elight to gentle	2.4	2.2	32	9	36	3	
•	000	gent le	*	9.9	23	33	91	2	

Sucke was detected earlier than emperature in the cabin in all eats. Similar trends in the wriation of smoke, temperature, and set that show that these parameters in related.

CONCLUSTORS

extremes.

6. Smoke was detected earlier than temperature in the cabin in all tests. Similar trends in the variation of smoke, temperature, and heat flux show that these parameters are related.

#### CONCLUSIONS

- 1. Given an external fuel fire much larger than an aircraft doorway, wind direction and door opening configuration play the dominant role in the development of the internal cabin hazard from the pool fire.
- 2. The symmetry plane calorimeter value of 1.8 Btu/ft2s found in earlier calm wind modeling tests appears to be a lower bound for full-scale tests using the same calorimeter value will go up with increased flame penetrations.
- 3. Comparison of the different tests demonstrates that increased fire penetrations shown by the ceiling calorimeter result in corresponding increases in the smoke and temperature hazards.


#### REFERENCES

Preliminary Wide Body (C133) Cabin Pittsburg, 1967.

- the hazard appeared between these Hazard Measurements During a Postcrash Fuel Fire, Federal Aviation Administration, National Aviation Facilities Experimental Center, Report NA-78-28-LR, 1978.
  - 2. Geyer, G. B., Effect of Ground Crash Fire on Aircraft Fuselage Integrity, Federal Aviation Administration, Report No. FAA-RD-69-46, 1969.
  - 3. Conley, D. W., Post-Crash Fire-Fighting Studies on Transport Category Aircraft, Federal Aviation Administration, Report No. FAA-RD-65-50, 1965.
  - 4. Sarkos, C. P., Titanium Fuselage Environmental Conditions in Post-Crash Fires, Federal Aviation Administration, Report No. FAA-RD-71-3, 1971.
- 5. Eklund, T. I., Pool Fire Radiation Through a Door in a Simulated Aircraft geometrical door size to fuselage <u>Fuselage</u>, Federal Aviation Admindiameter ratio. This symmetry-plane istration, Report No. FAA-RD-78-135, 1978.
  - 6. Marcy, J. F., A Study of Air Transport Passenger Cabin Fires and Materials, Federal Aviation Agency, Report No. FAA-ADS-44, 1965.
  - 7. Lehr, P. E., Burnett, R. W., and Zim, H. S., Weather, Golden Press, New York, page 125, 1965.
- 8. Emmons, H. W. and Ying, S. J., The Fire Whirl, Eleventh Symposium (International) on Combustion, page 1. Sarkos, C. P. and Hill R. G., 475, The Combustion Institute,

## APPENDIX A

LASER TRANSMISSOMETER DATA FOR BOTTOM LASER (L2) TESTS 3, 4, 9, 10, 13, AND 14






FIGURE A-2. TEST 4

FIGURE A-1. TEST 3




FIGURE A-3. TEST 9




FIGURE A-4. TEST 10




FIGURE A-5. TEST 14




FIGURE A-6. TEST 13

APPENDIX B
TEMPERATURE STRATIFICATION PLOTS



FIGURE B-1. TEST 3

B-1




FIGURE B-2. TEST 3




FIGURE B-3. TEST 4




FIGURE B-4. TEST 4




FIGURE B-5. TEST 9




FIGURE B-6. TEST 9




FIGURE B-7. TEST 10




FIGURE B-8. TEST 10




FIGURE B-9. TEST 13




FIGURE B-10. TEST 13

B-10




FIGURE B-11. TEST 14




FIGURE B-12. TEST 14